



Project Information

Project Name	Stellos Stadium ASTM F1936-19 g-max Impact Evaluation		
Client Info	R.A.D. Sports 171 VFW Drive Rockland, MA 02370	Site Info	Stellos Stadium 7 Stadium Drive Nashua, NH 03062
Report Date	10/2/2024	Test Date	10/2/2024
Report Status	Final	Job No.	100045/10223s
Prepared by	Michael Rocheleau Field Operations Manager		
Checked by	Jeffrey Gentile Operations Director		

Notes:

1. This report has been prepared by Firefly Sports Testing with all reasonable skill, care and diligence within the terms of the contract with the Client and within the limitations of the resources devoted to it.
2. This report is confidential to the Client and Firefly Sports Testing accepts no responsibility whatsoever to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.
3. This report shall not be used for engineering or contractual purposes unless signed by the Author and the Checker and unless the report status is "Final."

Summary

Firefly Sports Testing was commissioned to perform on-site g-max impact testing per ASTM F1936-19. A complete test was performed in accordance with the ASTM F1936-19 Standard. The results have been summarized in the quick reference table below. Test results herein reflect the performance of the points tested, at the time of testing and at the temperature(s) reported. Complete results and background can be found in the subsequent sections of this report.

Quick Reference Results Summary

	Average	(min)	Range	(max)	Max per ASTM
g-max (g's)	184	158	to	229	200
Infill Depth (mm)	31	25	to	36	n/a

Table of Contents

Project Information.....	1
Summary	1
General Information.....	2
Overall Photo	2
Average Results.....	2
Location Map	3
Results.....	3
Location Photos	4
Annex – Visual Inspection.....	5
Visual Inspection Photos	6
End of Report.....	7




General Information

Testing Device	ASTM F1936 Apparatus TRIAx 2010 Data Acquisition	Test Method	ASTM F1936-19 ASTM F355 Procedure A
Install Date	n/p	Test Date	10/2/2024
Field Orientation	End A= Southwest	Primary Sport	Football
Product Info	n/p	Infill System	Rubber & Sand
Underlayment	None	Air Temperature (°F)	53
Turf Cover %	n/a	Soil Moisture %	n/a
Humidity (%)	88	Weather Conditions	Partly Cloudy
Misc Field Notes	None	Technician	AD


Overall Photo



Average Results



Location Map



Results

Loc #	Location Description	Drop 1 g-max (g's)	Drop 2 g-max (g's)	Drop 3 g-max (g's)	Average g-max (g's)	Infill Depth (mm)	Surface Temperature (°F)
1	Goal Line, End A, center of field	194	204	209	207	28	65
2	10 Yard Line, End A, 63 ft from center of field to Side C	143	159	163	161	34	65
3	25 Yard Line, End A, 40 ft from center of field to Side C	155	173	174	174	29	65
4	Center of the field	210	228	229	229	25	65
5	25 Yard Line, End B, 63 ft from center of field to Side D	140	157	160	159	34	65
6	12 Yard Line, End B, center of field	192	213	215	214	25	65
7	35 Yard Line, Side D, 6 ft outside of the in-bounds line	144	157	158	158	34	65
8	37 Yard Line, End B, 40 ft from center of field to Side C	143	158	157	158	36	65
9	6 ft from Goal Line to the back of the End Zone, End A, center of field	155	176	180	178	31	65
10	6 ft from the back of the End Zone to the Goal Line, End B, center of field	181	201	207	204	30	65
Average					184	31	65

Note: Per ASTM F1936, the average g-max is the average of the second and third drops.

Location Photos



Location #1



Location #2



Location #3




Location #4



Location #5



Location #6



Location #7



Location #8




Location #9



Location #10

Annex – Visual Inspection



Item No.	X	Y	Length, X (ft)	Width, Y (ft)	Deviation Type	Comments
1	I.3	5			FL- Loose Fibers	White fibers loose around entire field
2	E	3.1	0.5	0.5	SF – Seam failure	
3	F	3.1	1	0.5	SF – Seam failure	
4	G	3.1	2	0.5	SF – Seam failure	
5	H.1	3.1	2	0.5	SF – Seam failure	
6	G.6	3.1	2	0.5	SF – Seam failure	
7	H.6	3.1	2	0.5	SF – Seam failure	
8	H.6	3.2	1	0.5	SF – Seam failure	
9	I	3.2	1	0.5	SF – Seam failure	
10	J	3.2	1	0.5	SF – Seam failure	
11	J.2	3.2	1	0.5	SF – Seam failure	
12	L	4.5	2	0.5	FW - Worn Fibers (High wear)	Yellow fibers across entire field degrading faster than green and white
13	J.6	5	5	5	FW - Worn Fibers (High wear)	
14	I	6.7	2	0.5	SF – Seam failure	
15	H	6.7	0.5	0.5	SF – Seam failure	
16	G.1	6.7	0.5	0.5	SF – Seam failure	
17	F.7	6.7	0.5	0.5	SF – Seam failure	
18	G	5	3	0.5	FW - Worn Fibers (High wear)	
19	F	6.7	0.5	0.5	SF – Seam failure	
20	E	6.7	1	1	SF – Seam failure	
21	D.2	6.7	2	2	SF – Seam failure	
22	D	6.7	1	0.5	SF – Seam failure	
23	C.4	5	1	1	SG – Gap in seam	
24	C.4	5	5	5	FW - Worn Fibers (High wear)	
25	C.4	5	5	5	IL– Lack of (Low) Infill	

Visual Inspection Photos



Item 1



Item 2



Item 3



Item 4



Item 5



Item 6



Item 7




Item 8



Item 9



Item 10



Item 11



Item 12



Item 13



Item 14



Item 15

ON-SITE TESTING g-MAX IMPACT EVALUATION



Item 16



Item 17




Item 18



Item 19



Item 20



Item 21



Item 22



Items 23, 24 & 25

End of Report